Blade Heat System Repair, part II




Greger Nilsson




Blade heat systems

- Hot air Enercon, Vestas
- Carbon heat mat, VTT, Nordex, Simens





Carbon heat mat inspections




Impact damage

Hotspot




Carbon heat mat inspections




Lightning



Damage on carbon fibre mat Hot Spot 34.5°C **\$FLIR**



Manufacturing of specimens






Impact and lightning damage








Fatigue testing of repairs





Repair of impact damage




Before repair

After repair


After fatigue testing



Carbon heat mat repair of a impact damage




Before repair



After repair




Carbon heat mat repair of a lightning damage



inspection & repair

Damage in root blade heat connection






Damage in tip blade heat connection





New blade heat connections



inspection & repair

Winter repair






Inspection of blade heat systems

- Thermal camera from some access methods
- Long range thermal camera
- Thermal camera from drone




Long range thermal camera




Blade Solutions

Inspction from rope access





Inspction from rope access







Live demonstration of blad heat system and repair of damage

At Energiservice stand in the exibition hall between 14:30 to 15:30





Thank for your attention



