Addressing Lightning Risk

A shocking case study on how a wind farm lost insurance for lightning strikes and got it back again!




ANDREAS CHRISTAN ESPERSEN <u>ACE@WINDPOWERLAB.COM</u> +45 31 45 32 55



ST. KONGENSGADE 58 D - 1264 COPENHAGEN K – DENMARK - +45 31321006 - MBK@WINDPOWERLAB.COM - WWW.WINDPOWERLAB.COM

Courtesy: Lachlan Ross

Types of lightning







Meet the wind farm Lightning Valley




Lightning protection system certifications limits

Lightning parameter certification limits for LPL 1 of the IEC standard*.	
Peak current	-100 to 200 kA
Average steepness	200 kA/µs
Specific energy	10 MJ/ Ω
Total charge	300 C






A global outlook - Lightning density map




Global Blade Experts

Source: Vaisala

Lightning from a swedish point of view







Seasonal variation of strikes





Global Blade Experts



Insurance often negotiated on a yearly basis

Increase in payouts related to blade damages caused by lightning

Source: news.northeastern.edu



Examples of damages caused by strikes

FLASH OVER DAMAGE RELATED TO DAMAGED DOWN CONDUCTOR CABLE



SPLIT TRAILING EDGE



DELAMINATION

FLASH OVER DAMAGE





Global Blade Experts


Lightning surveillance

Notifications

Targeted inspections

Act in time

Global Blade Experts







Prudent Operator



